

## ATARI INTER-OFFICE MEMO

TO : Distribution

FROM : Pat Brosnan

Date : Nov, 26, 1985

Subject : Conversion of Pole Position II boards from Japanese to English.

Fourteen changes are to be made to convert these boards from Japanese to English. Thirteen will be Eprom changes which we can reprogram inhouse. The other one will have to be ordered. The modifications to the CPU and Video boards are as follows :

<u>CPU Board</u> :	<u>Remove</u>	<u>Insert</u>	<u>Location</u>	
	FP1-11	136014-147 ✓	2E	SOUND
	FP1-12	-	2F	} NOT NEEDED FOR CHEERING CROWD
	FP1-13	-	1E	
	FP1-14	-	1F	
	PP4-5	136014-178 ✓	4M	} FOR INSTRUCTION AT THE START OF THE GAME AND FOR ATARI NAME.
	PP4-6	136014-179 ✓	4L	
	PP4-7*	136014-184 ✓	3M	
	PP4-8*	136014-185 ✓	3L	

\* These Eproms are 2732's they will be replaced by 2764'S.

Video Board :

<u>Remove</u>	<u>Insert</u>	<u>Location</u>	
PP1-19	136014-166 ✓	4N	* MAINLY TO CHANGE "PREPARE TO QUALIFY" SIGN TO ENGLISH.
PP1-20	136014-167 ✓	4M	
PP1-21	136014-168 ✓	3N	
PP1-22	136014-169 ✓	3M	
PP4-23	136014-174 ✓	2M 2M*	* HAVE TO CHANGE OTHERS BECAUSE OF THE ABOVE BEING CHANGED OTHERWISE SIGNS WILL LOOK WRONG.
PP4-24	136014-175 ✓	2M 2M*	
PP4-25	136014-170 ✓	1N	
PP4-26	136014-171 ✓	1M	
PP4-6	136014-192**	6M*	

\*\* This the IC which will have to be ordered as we are unable to copy it.

NOTE: There is an added connector put on the CPU board for some reason. We do not have any use for this connector so it will be removed.

cc. F. Murphy, J. Nugent, M. Nevin, A. Doyle

\*  
28165 ATAR EISSSS

T0015

TO: ATARI IRELAND LTD MR. MIKE NEVIN  
FROM: HIDE NAKAJIMA  
DATE: NOV. 15, '85

C/MN.  
cc: JN  
PB  
FM  
AD  
PP  
DS.

150 POLE POSITION-II PCBS WERE SHIPPED 11/15/85.  
ADDITIONAL 50 PCS WILL BE SHIPPED 11/20/85.  
ONLY DIFFERENCES BETWEEN US VERSION AND JAPANESE VERSION ARE:  
1. VOICE 2. BILL BOARDS IN THE BACK GROUND OF THE RACE TRACK.

ALL THE BILL BOARDS ARE HOWEVER WRITTEN IN ENGLISH WHICH NEED NO CHANGES.

VOICE YOU'LL HERE IS A LADY SAYING ''QUALIFYING ROUND. START.'' IN JAPANESE.

OF COURSE IT IS BETTER IF NAMCO CAN CHANGE IT TO ENGLISH BUT IT SEEMS IMPOSSIBLE TO DO SO AT THIS TIME. BESIDES THIS JAPANESE ANNOUNCEMENT IS NOT A CRITICAL DEFECT OF THE GAME, AT ALL. SO PLS TALK TO GOLDSTEIN THAT HE SHOULD NOT WORRY ANYTHING ABOUT THE VOICE.

IN FACT, ALL POLE POSITION COPIES WHICH WERE SMUGLED AND SOLD IN EUROPE (OVER 1000 PCS?) WERE WITH JAPANESE VOICE. NO JAPANESE LAUNGAGES NOR VOICES BESIDE THIS ARE NOT IN THE PCBS ACCORDING TO THE BEST OF MY KNOWLEDGE. IN ADDITION, THE PEOPLE HERE HAVE BEEN TRYING SO HARD TO GATHER ALL 200 PCBS FOR IRELAND AND TOO LATE TO CHANGE OUR ORDER TO THEM.

YOUR UNDERSTANDING OF THE SITUATION AND YOURS AND DEVE'S EXTRA EFFORT TO MAKE GERALD UNDERSTAND THAT THERE SHOULD BE NO PROBLEM WILL BE APPRECIATED.

THANKS AND REGARDS,  
HIDE NAKAJIMA IN TOKYO

VIDEO BOARD PROBLEMS.

- 1) "PREPARE TO QUALIFY" IN JAPANESE
- 2) "Push Pedal TO START"

.....  
1) can be changed.

Pat  
File in my Pole Position  
Manual

c.c. F. Murphy  
M. O'Rourke  
B. Egan  
E. McGrath

Inter-Office Memo

ATARI  
Games Division

To: Pat Bradman

From: Sam Deus *Sam (DAVE WIEBENSON'S INPUT)*

Subject: Pole Position M.O. Problems

Date: June 25, 1984

1. Tearing of Cars and Signs:

- a. 9H, 9J, 10H, 10J, 10K, 10L, should be S161 - not National parts.
- b. 8D should be S158. A F158 works even better here.
- c. 7C, 6A should be S04. I've seen a 100 PF cap on Pin 4 to GND sometimes help, but officially this is not a good practice.
- d. 8B should be S00. (S PART)
- e. Custom 04 at 7E is a rare problem. Try different date code.

2. Spotting of Cars and Signs:

- a. 9F, 10F must be 55ns parts.
  - b. See la, lc, ld.
3. Look at signal on 9L-9. Should be clean pulse. If pulse and spike then try lift 9L-9 and connect 10B-5 to 9L-9.
  4. On PPII, it is normal for a sign to tear only near or approaching the bridge with people over the course. This happens because too many motion objects are being displayed.

SD:jdh

29-6-84 Problem with Custom 04 with date codes 86-88.

## FIELD SERVICE

### Inter-Office Memo

ATARI 21 NOV 1983  
Games Division

To: Darl Davidson  
From: Sam Deus *Sam*  
Subject: Pole Position P.C. Board Problems

*CC. M.P.G.R.  
P. BRONAN  
F. Murphy  
K. Hayes.*

Date: 11/3/83 *T. Guerin*

Our last run of Pole Position boards showed a high percentage of failures. The symptom of the failure is random RAM errors on the power up. This problem has been in existence since early builds, but never as severely as this run. Dave and I have been examining the problem very closely for the past few days. Here is the summary:

- 1.) Problem symptom: RAM failures in the self test on power up.
- 2.) Actual problem: The way that NAMCO designed the logic. The section of the logic using two PROMs (135, 136) as chip select and buffer enable decoders. Random glitches on the outputs of the PROMs generating improper chip selects at inappropriate times causing data to change in the RAMs.
- 3.) Why has this problem appeared all of a sudden?: Because the combination of IC's that we are using are very sensitive to the glitches. These include very fast Harris PROMs that react to changing address lines and produce excessive noise.
- 4.) Immediate solution: Currently bypassing one of the address lines with a 150 pF capacitor. This is not an ultimate solution but keeps the line going.
- 5.) What is the final solution?: Of course it would be a re-design, but that is out of the question. The reasonable solution is to use a different manufacturers PROMs which are slower than Harris parts. The first time National parts could become of some use. Because the National parts are slower, they operate somewhat like a filter and do not generate as many glitches. Unfortunately, all we have in inventory is Harris parts and there isn't enough time to get any Manufacturer's part into production in time to catch the last of the build.

I anticipate that when this batch of boards hits the market that you will get a small percentage of failures and complaints from the field. Be prepared to explain to our customers what the problem is and how to fix it. This is all I can think of that we can do. Please advise me if you see any other way that we can be of some help.

SD:br

*CC: JOHN RAY  
EMONN MC GRATH  
DICK REBERT  
SILVIA W. HANICAT*

*WOODY WOODWORTH  
FRANK BECKER*

Inter-Office Memo

ATARI  
Games Division

03 OCT 1983

To: Pat McSweeney

From: Sam Deus *Sam*

Subject: Pole Position II Upgradability

Date: 8/25/83

Since Pole Position II is coming in the very near future, I thought it would be a good idea to get the Pole Position boards ready now for upgrading to Pole Position II. My reasons for implementing this are as follows:

To upgrade the existing Pole Position boards, the labor cost will be considerably larger than if we were to exchange EPROMs and PROMs on Pole Position II ready boards.

To upgrade the Pole Position boards that are already built will require the following:

- A) Unsoldering 7 PROMs and soldering 7 new ones.
- B) Unsoldering two 24 pin sockets and soldering two 28 pin sockets.
- C) Soldering three new 28 pin sockets into currently unused locations (after clearing the solder filled holes).
- D) Replacing 16 new EPROMs and removing 12 old ones.

Unbuilt boards can be made ready for Pole Position II upgrading by stuffing 12 sockets for the cost of about 90 cents. This may not save any money directly to Atari, as a matter of fact, it will add to our cost, unless we have to do the upgrading at inventory level. However, it will have indirect benefits and will save alot of money for our future customers and 2000 less headaches to our field service department. If you agree with me on this, please let me know and I will give you the information on what needs to be done.

SD/br

cc: Darl Davidson  
Singh Mangat  
Dick Maslana  
John Ray  
Dan Van Elderen  
Woody Woodworth

cc. *Eamon*  
*Martin*  
*Frank*  
*Elaine*

Inter-Office Memo

A T A R I  
Coin-Operated Games Division

**FIELD SERVICE**  
**22 AUG 1983**

To: Nancy Perkins

From: Sam Deus *Sam*

Subject: National I.C. 74LS08 *LOCATION 6C* Date: 7/27/83

*cc. M.D.O.F.*

We are experiencing 30% failure on the Pole Position video boards at the final test. Dave Wiebenson's investigation showed that the problem is being caused by a combination of glitch and a sensitive IC (National 74LS08) on the P.C. board. This part is currently on the A.V.L. list. We do not have substantial evidence to say that the part is defective or out of spec. However, the best solution to the problem is not to use the part at the present time until we find a better solution to control the documentation. It is best to replace all of the National IC's at the problem location of the video boards currently in production to avoid further problems in the field.

SD/br

cc: Dean Charrier  
Rich Cocciolone  
Darl Davidson

PROBLEM

*INTERMITTENT RAM 0 DISPLAYED ON POWER-UP  
-SOMETIMES CLEARS.*

*Copy all FSP  
Elaine  
Jeanette  
Mike*

INTER-OFFICE MEMO



TO : M. O'Rourke, T. Guerin, Files  
FROM : Eamonn McGrath *EM*  
SUBJECT : Pole Position USA Board Problems

DATE : 14th February, 1983

We experienced a greater than average Board failure rate in the first run of Atari Boards. This was attributed to a great extent to Audio Problems.

When I reported this to Sam Deus ( Project Engineer ), he was surprised that this audio problem had not been fixed by PCB test in the USA. They were aware of the problem and had a fix for it. This Audio problem will be fixed on Rev C PCB's. The bad Audio was apparent in all cases on immediate power-up and these boards should not have passed inspection in the PCB test area in USA.

For the record, the following are the three possible fault areas and solutions, as discussed with Sam Deus on 10/2/83.

Problem 1. Bad Audio on 1 channel:  
Timing Problem on Sound Rams

Solution: Add 220PF Cap between C6 and Ground on CPU PCB.  
(Page 6B of SP. 218).

Problem 2. Color Dots on Motion Objects - Timing problems, parts specially selected.

Solution: Replace LS158 101th S158 at 8D on video PCB.  
(Page 15A of SP.218).

Problem 3: Odd colors on CARS when using Mask Programmed Roms

Solution: Cut and lift Pin 1 of 11L and tie to Ground on Video PCB.  
(Page 14A of SP. 218).

EMCG/vh

Eamon U



Coin Operated Games Division

# Inter Office Memo

To: Field Service Personnel

08 JUN 1983

From: Bernie Barranger *BB*

Subject: Pole Position

Date: May 25, 1983

Some power supply assemblies are developing lug contact problems on the bridge rectifier terminal. The heat generated at the terminal can melt the fuse and transformer wire insulation.

The solution at present is to inform the game owners to solder the transformer wire directly to the terminal.

BB/pd



# Inter Office Memo



Coin Operated Games Division

23 DEC 1982

To: Darl Davidson

From: Bob Salmons

Subject: Pole Position Score-To-Date

Date: Dec. 8, 1982

PROBLEM: Some Pole Position games do not retain high score-to-date memory. The game allows you to write your name, but it does not save in memory.

SOLUTION: American Board: Replace CR6 a 1N4728 3.3v Zener Diode on CPU board to a 1N748A 3.9v 1/4watt Zener Diode or a 1N5228 3.9v 1/4watt Zener Diode.

Japanese Board: Replace D10 a 1N4728 3.3v Zener Diode on CPU board to a 1N748A 3.9v 1/4watt Zener Diode or a 1N5228 3.9v 1/4watt Zener Diode.

BS/ca

cc: Jim Alexander  
Russ Mac Donald  
Bernie Barranger  
Frank Becker  
Russell Gorr  
Eamonn McGrath  
Sunnyvale Techs  
New Jersey Techs



EXTRA  
EXTRA  
EXTRA

READ ALL ABOUT IT

IMPORTANT

08 FEB 1983

Pole Position Test Plugs

The CTS/1 Regulator Audio Board will not provide sufficient current for both the CPU and Video Board + 5 volt lines.

Use a second Regulator / Audio Board to provide +5 volts for the Video PCB.

Double crimp this + 5 volts onto terminal 3 of the 3 position Amp Video Power Connector, and ground to pin 2.

FIELD SERVICE BULLETIN



Edmond

# Inter Office Memo

**FIELD SERVICE**  
**14 MAR 1983**



Coin Operated Games Division

To: Field Service

From: Bernie Barranger *BB*

Subject: Pole Position ROM Failure Date: March 4, 1983

Incorporate the following chart in the manual.

### SELF TEST SCREEN DISPLAY FAILED ROM CPU BOARD

<u>DISPLAY</u>	<u>ATARI PCB</u>	<u>NAMCO PCB</u>
ROM 0	7H	6H
ROM 1	7F	5H
ROM 2	3E	8M
ROM 3	4E	8L
ROM 4	3D	7M
ROM 5	4D	7L
ROM 6	3L	4M
ROM 7	4L	4L
ROM 8	3K	3M
ROM 9	4K	3L

BB/ca

# Inter Office Memo

**FIELD SERVICE**  
**22 NOV 1982**



Coin Operated Games Division

To: ~~Sam Deus~~

From: Chris Downend

Subject: Coin Input Problem on Pole Position

Date: 3 November 1982

I recommend the following solution. This is a modification of Solution #5 from your memo dated November 2, 1982. Build our games in the factory as follows:

- A. Sitdown Games (These will be set on 50¢ play most of the time.)
  1. Disconnect the wire from Coin Switch 2 and connect it to the same input as Coin Switch 1. This means that a coin placed in either coin mechanism registers in the same coin counter and the problem disappears. However, it creates a problem with the manual. The operator also loses the ability to put different denomination coin mechanisms in the same game.
  2. Add a stuffer sheet to the manual explaining to the operator that the coin option switch listed for "Coin 1" work for both coin mechanisms and the option settings listed under "Coin 2" do not apply.
- B. Upright Games (These will be on 25¢ play most of the time.)
  1. Leave the coin switches connected to separate inputs with separate option selections. This creates a problem if a game is placed in 50¢ play.
  2. Add a stuffer sheet to the manual warning the operator that, "In 2 Coin/1 Credit or 3 Coin/1 Credit or 3 Coin/2 Credit or 4 Coin/3 Credit coin modes, the multiple coins must be placed in the same coin mechanism." Also explain how to wire both coin switches to the same input.

I think this is the best solution since:

- Solution #1 cannot happen in time.
- Solution #2 creates a less reliable product (2 coin mechs are more reliable than one).
- Solution #3 advertises we screwed up.
- Solution #4 advertises we screwed up and irritates operators.

CD:cak

cc: S. Calfee  
B. Falconer  
M. Fujihara  
D. Hawes  
D. Van Elderen

lot. 21, 1784

# Pole Position Video Board Manufacturing Defects

FIELD SERVICE

07 FEB 1983

The principle problem with the Pole Position Video boards was a masking error; VSYNC was being disrupted by a signal which was being output from pin 8 of IC 2J. Pin 8 of 2J had to be cut & lifted from the feed thru pad because the VSYNC trace was erroneously masked & subsequently etched from pin 17 of IC 2F (custom IC 07) to pin 8 of IC 2J (74LS10) which is supposed to be an unused output, not an input. See page 3 of 10 (Video PC BD schematics)

