

**Distributor Notice**

**Date: 05-08-00**

**Game: TouchMaster 8000**

**Subject: Revision 9.04**

**TouchMaster 8000 Update**

**The TouchMaster 8000 is being updated to improve the performance of the Power Cell game.**

**The update consists of 2 eproms that are at locations U51 & U52 on the CPU board.**

**You will be issued an RMA for the return of the replaced EPROMS from your Customer Service representative.**

**Depending on your jurisdiction (country codes) and cash box setup, you may receive specific sets of eproms to satisfy those needs. Keep this in mind when sending out the updates.**

**If you require additional information for this update, contact your Midway Customer Service representative or our Field Service Support group.**

**Listed below is the Product Code and Kit Required to Update:**

**Product Code Kit Number**

**63394 A-23904**

**69494 A-23908**

**83320 A-23904**

**83321 A-23904**

**67494 A-23909**

**60294 A-23911**

**67694 A-23910**