

# Bally

MIDWAY MFG. CO.

---

10601 W. Belmont Avenue  
Franklin Park, Illinois 60131  
Telephone (312) 451-9200



October 27, 1983

S E R V I C E B U L L E T I N

GAME:       ASTRON BELT

SUBJECT:    IC-1 BAD IN SELF TEST

1. IC-1 (5473B) has been newly added to your game's EPROM PC Board.
2. This can cause a properly functioning game to give a false error message in the self test mode.
3. As long as your game is functioning properly, disregard this message.

Andy Ducay  
Technical Service Manager

AD/dd