


# BULLETIN

From Atari Customer Service



 A Warner Communications Company

B-A016

Date: June 20, 1979

## HERCULES<sup>TM</sup>

Due to the types of components used on this game, there is a vibration in excess of that found on a standard pin-ball machine.

Therefore, a regularly scheduled preventive maintenance routine is required. Every two or three weeks, all play-field components should be checked. Particular attention should be given to areas subject to direct hits from the ball or action items such as thumpers, etc.

Your cooperation in this will decrease your downtime by minimizing nuisance-type service calls.