

**Service Bulletin #43**

To: Service Managers
From: Data East Pinball Service Department
Date: June 22, 1993
Subject: Failure of switch #37 (Center Scoop) on Jurassic Park Pinball.

Symptom:Center scoop switch fails, preventing features from being acquired by shooting the ball into the control room.

Cause:Broken Diode on center scoop switch.

Cure: Replace the damaged diode. To prevent shock damage to the diode, apply a silicon rubber compound to the points where the diode is formed to absorb the impact.

Note- All of these changes have occurred by game Serial # 87390.

If you have any further questions, please contact Jim or Arnie at 800-542-5377.