


BULLETIN

From Atari Customer Service



 A Warner Communications Company

JAX
MIAMI
PALATKA
RAINBOW
TEL ROOM
SVC. DEPT
PARTS

DATE May 7, 1982

DIG DUG™

To eliminate any static related problems on Dig Dug™, please do the following.

Solder a .1µf capacitor between pins 5 and 7 of the 74128 located in position A/B-3 on the PCB.

Thank you,

A handwritten signature in cursive script, appearing to read 'Fred McCord'.

Fred McCord
Atari Field Service

1105 N. Fair Oaks . Sunnyvale, California 94086 . (408)745-2900 . (800)538-1611