

SERVICE BULLETIN 01 (Reprint)

FROM: Pete Gustafson, Field Service Mgr.

TO: Service Managers

DATE: April 12, 1988

RE: Secret Service - Playfield Ball Trap

Problem: Ball gets stuck on top of clear plastic above white house (see Fig. 1).

Solution: Call Field Service at 1-800-KICKERS (1-800-542-5377) and request a Secret Service ball trap modification kit. The kit consists of the following parts:

Quantity	<u>ltem</u>	Part Number
1 1 1 1	Spacer Screw Flat Washer Star Washer Nut	254-5000-01 237-5506-00 242-5005-00 246-5000-00 240-5004-00
1	Installation Instructions (No P/N)	

Note 1: This only affects a few Secret Service games. The majority of games had this modification installed at the factory.

Note 2: Please have the game serial number available when calling for this modification.