

APRIL 10, 1981

PART NUMBER CORRECTION

PLEASE INSERT THIS NOTICE IN THE FRONT OF YOUR RED BARON MANUAL (TM-171) AND WRITE CORRECT PART NUMBER IN YOUR MANUAL.

CORRECT THE PART NUMBER FOR THE CONTROL HANDLE ON PAGE 30, FIGURE 18 AS FOLLOWS:

USE 035995-01,-02 INSTEAD OF 036995-01,02

ATARI CUSTOMER SERVICE

1105 Fairoaks Avenue Sunnyvale, CA 94086 408/745-2900 or foll free 800/538-1611