BULLETIN

om Atari Field Service



DATE August 30, 1983

Posts John Tech John cleck

STARWARS

The Following Items Require Your Immediate Attention!

ATARI Color X-Y Monitor (STAR WARS* only)

High-Voltage Board

Change capacitors C3 and C4 from $100~\mu\text{F}$ at 35 volts to $220~\mu\text{F}$ at 35 volts, with a low Equivalent Series Resistance (ESR) Rating. The Atari part number is 123009-227. The following manufacturers' capacitors will work:

Illinois Capacitor

Nichicon

227 RMR 050M (50 volts)

UPA1V221M (35 volts)

Deflection Board

When servicing the Deflection board, please change diodes CR2 and CR11 to Type-1N4148, Atari part number 131033-001. The old diodes (Type-1N914) will open, causing fuses F1 and F2 to blow.

*© 1983 Lucasfilm Ltd. & Atari, Inc. All rights reserved. Lucasfilm trademark used under license.

1105 N. Fair Oaks . Sunnyvale, California 94086 . (408) 745-2900 . (800) 538-1611