



No. 31460-A
Power Distribution Panel Assembly

| Part No. | Description |
|----------|-----------------------------------|
| 1 | 31461 Control Circuit Transformer |
| 2 | 19272 Miniature Outlet |
| 3 | 17596 4 Prong Socket |
| 4 | 19272 Miniature Outlet |
| 5 | PH-3722 4 Prong Socket |
| 6 | 18414 6 Prong Socket |
| 7 | 19008 6 Prong Jones Socket |
| 8 | 5T-4321 1 1/2 Amp. Fuse |
| 9 | 5T-3090 3 Amp. Slo-Blo Fuse |
| 10 | 19272 Miniature Outlet |
| 11 | PH-3523 3 Amp. Fuse |
| 12 | 5T-3092 10 Amp. Fuse |
| 13 | 19272 Miniature Outlet |
| 14 | 31242 Tip Jack |



No. 31460-A Power Distribution Panel Assembly

| Part No. | Description |
|----------|-----------------------------------|
| 1 | 11555 Fuse Holder |
| 2 | 31225 Power Rectifier |
| 3 | 18859 Start Relay |
| 4 | 18417 .01 MFD. 400 V. Capacitor |
| 5 | 15476 .002 MFD. 1200 V. Capacitor |