

# BULLETIN

From Atari Field Service



DATE August 30, 1983

## STAR WARS

**The Following Items Require Your Immediate Attention!**

### **ATARI Color X-Y Monitor (STAR WARS\* only)**

#### **High-Voltage Board**

Change capacitors C3 and C4 from 100  $\mu$ F at 35 volts to 220  $\mu$ F at 35 volts, with a low Equivalent Series Resistance (ESR) Rating. The Atari part number is 123009-227. The following manufacturers' capacitors will work:

Illinois Capacitor  
Nichicon

227 RMR 050M (50 volts)  
UPA1V221M (35 volts)

#### **Deflection Board**

When servicing the Deflection board, please change diodes CR2 and CR11 to Type-1N4148, Atari part number 131033-001. The old diodes (Type-1N914) will open, causing fuses F1 and F2 to blow.

*1983 Lucasfilm Ltd. & Atari, Inc. All rights reserved. Lucasfilm trademark used under license.*

1105 N. Fair Oaks . Sunnyvale, California 94086 . (408)745-2900 . (800)538-1611